Bad MMSC

Published 10/20/2004

Symptom(s):

Bad MMSC
MMSC has no power
No response from MMSC

Fact(s):

SGI Origin 2000
Silicon Graphics Onyx2
Multi-Module System Controller (MMSC)

SGI Solution:

Replace MMSC module pn: 041-0229-002

Additional Details

Creation Date	07/21/2003 04:44 AM
Last modification	01/15/2016 04:29 PM
Published Date	10/20/2004
Products	• Servers and Clusters • SGI Origin/Onyx • Origin/Onyx Server • Workstations • SGI Tezro • O2 • Octane
Categories	• Knowledgebase • Technical Solution